

Data Management, Inc.
DIR-TSO-3867 Appendix C Pricing Index

PRODUCT DESCRIPTION Manufacturer: Data Management, Inc.	Part Number	Discount % off MSRP		
GT-400 / 100 Series Hand Scanner	46-400	25.00%		
GT-400 / 200 Series Hand Scanner	46-405	25.00%		
RDT Reader Retrofit Upgrade (Proximity)	46-223	25.00%		
RDT Digital I/O Retrofit Upgrade (12V D.O K54)	46-813	25.00%		
RDT Digital I/O Retrofit Upgrade (12V D.O K27)	46-510	25.00%		
External Indala Proximity Reader	46-950	25.00%		
External ioProx Reader	46-995	25.00%		
External AWID Proximity Reader	46-997	25.00%		
External KERI Proximity Reader	46-996	25.00%		
External HID Proximity Reader	46-990	25.00%		
External HID Proximity Reader w/ Keypad	46-998	25.00%		
External Magnetic Badge Reader	46-119	25.00%		
External Bar Code Reader	46-160	25.00%		
Multi-Function Alert w/ 20ft Cable	46-121	25.00%		
Desktop Mount for RDT 100/200 Series	46-991	25.00%		
RDT Wall Mount	46-310	25.00%		
RDT Wall Mount Key (Set of 2)	46-101	25.00%		
Symbol CCD Mid Range Scanner	46-992	25.00%		
Daughter Board- Serial Handscanner Support (K52)	46-182	25.00%		
Daughter Board- DIDO Relay for Externally Powered	46-183	25.00%		
RDT 400 PIN (Fallback)	144-105	25.00%		
RDT 400 Magnetic	144-106	25.00%		
RDT 400 Bar Code	144-107	25.00%		
RDT 400 HID Proximity	144-112	25.00%		
RDT 400 Biometric	144-200	25.00%		
RDT 300 PIN	145-105	25.00%		
RDT 300 Magnetic	145-106	25.00%		
RDT 300 Bar Code	145-107	25.00%		
RDT 300 HID Proximit	145-112	25.00%		
RDT 300 Biometric	145-200	25.00%		
RDT 400 Touch PIN (Fallback)	244-105	25.00%		

*Important Note: Vendors quote to DIR customers shall include the DIR administrative fee. The fee will be added after discount off MSRP is applied.

Data Management, Inc.
DIR-TSO-3867 Appendix C Pricing Index

Hardware Maintenance (Expedited Depot Repair)	1099-250	16% of total system cost			
Software Maintenance (Product Addition)	1099-320	Prorated based on the remainder of contract term			
Hardware Maintenance (Product Addition)	1099-340	Prorated based on the remainder of contract term			
Support Incident	1099-100	2% of total system cost			

*Important Note: Vendors quote to DIR customers shall include the DIR administrative fee. The fee will be added after discount off MSRP is applied.